



Loader PPE (Personal Protective Equipment)







G.051.03

PROTECTIVE CLOTHING


Wear OSHA or local governing body-approved protective clothing when working on or near this machine, such as


- ear protection
- hard hat
- gloves
- orange vest
- goggles
- steel-toed shoes

Wear snug, protective clothing that is belted where required.

Remove jewelry before working on or near this machine.

Identify the PPE Being Worn





HARD HAT WITH EYE/EAR PROTECTION

SNUGG CLOTHING

STURDY GLOVES

NO CUFFS

SAFETY BOOTS